

**DEPARTMENT OF THE ARMY**  
**U. S. Army Corps of Engineers**  
**Washington, DC 20314-1000**

EM 200-1-7

CEMP-RT  
CECW-E

Manual  
No. 200-1-7

1 February 2001

**Environmental Quality**  
**PERFORMANCE EVALUATION (PE) PROGRAM**

TABLE OF CONTENTS

	<u>Page</u>
Chapter 1. Introduction .....	1-1
1.1. Purpose .....	1-1
1.2. Applicability .....	1-1
1.3. Distribution Statement .....	1-2
1.4. References .....	1-2
1.5. Manual Overview and Scope .....	1-2
1.6. Acronyms and Definitions .....	1-2
1.7. Roles, Responsibilities, and Qualifications .....	1-3
1.8. Fees, Budget, and Funding .....	1-4
1.9. Effective Date and Amendment .....	1-4
Chapter 2. Characteristics of PE Samples .....	2-1
2.1. Definitions of PE Samples .....	2-1
2.2. Purposes of PE Samples .....	2-1
2.3. Types of PE Samples .....	2-1
2.4. Requirements of PE Samples .....	2-3
Chapter 3. Design of PE Samples .....	3-1
3.1. General Design Considerations .....	3-1
3.2. Specific Design Considerations .....	3-1
3.3. Customization .....	3-10
Chapter 4. Preparation of PE Samples .....	4-1
4.1. Selection of PE Sample Matrices .....	4-1
4.2. Selection of Chemicals and Reagents .....	4-2

4.3. Facility and Equipment Requirements .....	4-4
4.4. Preparation of PE Samples .....	4-6
	<u>Page</u>
4.5. Handling and Storage of PE Samples .....	4-12
Chapter 5. Certification of PE Samples .....	5-1
5.1. Initial Verification of PE Sample Composition .....	5-1
5.2. Ensuring Homogeneity, Stability, and Reproducibility .....	5-2
5.3. Testing for Homogeneity, Stability, and Reproducibility .....	5-5
5.4. Determination of Reference Values and Acceptance Limits .....	5-7
5.5. Hybrid Approach .....	5-11
5.6. Statistical Analysis .....	5-12
5.7. Other Considerations .....	5-13
5.8. Documentation .....	5-14
5.9. Standard Operating Procedures .....	5-15
5.10. Confidentiality and Ethical Considerations .....	5-16
Chapter 6. Use of PE Samples .....	6-1
6.1. Pre-Contract Proficiency Testing .....	6-1
6.2. Post-Contract Performance Monitoring .....	6-8
6.3. Complaints and Corrective Actions .....	6-9
Appendix A References .....	A-1
Appendix B Abbreviations, Acronyms, and Symbols .....	B-1
Appendix C Soil Cleaning Procedures .....	C-1
Appendix D Determination of Appropriate Particle Size of PE Samples .....	D-1
Appendix E Statistical Analysis .....	E-1
Appendix F Statistical Tables .....	F-1

List of Tables

Table		<u>Page</u>
6 -1.	Validation Parameters . . . . .	6 -8
D-1.	“f” Values for Different Particle Shapes . . . . .	D-3
D-2.	Maximum Allowable Particle Size That Can Be Accommodated by a Given Subsample Mass at Various Percent Relative Standard Deviation (RSD) . . . . .	D-5
E-1.	Example of Normal Probability Plot . . . . .	E-3
E-2.	Example of Homogeneity Test . . . . .	E-9
E-3.	ANOVA Table for Homogeneity Test . . . . .	E-10
E-4.	Example of Stability Test . . . . .	E-12
E-5.	Example of Student’s Two-Sample $t$ Test . . . . .	E-13
E-6.	Example of Satterthwaite’s $t$ Test . . . . .	E-15
E-7.	Example of Trend Test . . . . .	E-18
F-1.	Critical Values for Grubbs’ Test . . . . .	F-1
F-2.	Percentiles of the F Distribution . . . . .	F-2
F-3.	Critical Values of Student’s $t$ Distribution . . . . .	F-5
F-4.	Probabilities for the Small-Sample Mann-Kendall Test for Trend . . . . .	F-6
F-5.	Factors for Determining Two-Sided Prediction Intervals for the Next Observation Given Previous Sample of Size $n$ . . . . .	F-7

EM 200-1-7  
1 Feb 01

### List of Figures

Figure	<u>Page</u>
E-1. Normal Probability Plot .....	E-3